







LC25

PC208/210

	LC25
Torch (Hand 3m) (1pc)	PTH-C25A-SL-3MR
Handle (1pc)	W0300601R
Head (1pc)	W0300615R
Cable (3m) (1pc)	W0300616R




svetskompaniet.se

	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)	Retaining Cap (blister 1pc)	Spacer (blister 1pcs)
					
Cutting process 25A	W03X0893-75A	W03X0893-5R	W03X0893-76A	W03X0893-77A	W03X0893-78R











LC40 & LC60

PC620

	LC40	LC60
Torch (Hand 6m) (1pc)	PTH-040A-CX-6MA	
Torch (Hand 7.5m) (1pc)		PTH-060A-CX-7M5A
Torch (Hand 15m) (1pc)	PTH-040A-CX-15MA	PTH-060A-CX-15MA
Handle (1pc)	W0300601R	
Head (1pc)	W0300600R	
Cooling Kit (blister 1pc)	W03X0893-4R	
Cable (7.5m) (1pc)	W0300604R	
Cable (15m) (1pc)	W0300606R	
Connector (1pc)	W03X0934-2R	W03X0934-4R




svetskompaniet.se

Cutting process	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)			Retaining Cap (blister 1pc)		Spacer (blister 2pcs)	Shield Cap (blister 2pcs)	
										
40A	W03X0893-1A	W03X0893-5R		W03X0893-2A		W03X0893-10A		W03X0893-14R		
50A	W03X0893-1A	W03X0893-5R		W03X0893-3A		W03X0893-10A		W03X0893-14R		
60A	W03X0893-1A	W03X0893-5R		W03X0893-15A		W03X0893-10A		W03X0893-14R		
Dir Contact 25A	W03X0893-1A	W03X0893-5R	W03X0893-18A			W03X0893-10A				
Dir Contact 40A	W03X0893-1A	W03X0893-5R	W03X0893-8A			W03X0893-10A				
Contact 50A	W03X0893-1A	W03X0893-5R			W03X0893-6A		W03X0893-11A			W03X0893-7A
Contact 60A	W03X0893-1A	W03X0893-5R			W03X0893-17A		W03X0893-11A			W03X0893-7A
Gouging	W03X0893-1A	W03X0893-5R			W03X0893-9A		W03X0893-11A		W03X0893-13A	

LC40M & LC60M

PC620

	LC40M	LC60M
Torch (Machine 6m) (1pc)	PTM-040A-CX-6MA	
Torch (Machine 7.5m) (1pc)		PTM-060A-CX-7M5A
Torch (Machine 15m) (1pc)	PTM-040A-CX-15MA	PTM-060A-CX-15MA
Positioning tube (1pc)	W0300603R	
Head (1pc)	W0300602R	
Cooling Kit (blister 1pc)	W03X0893-4R	
Cable (7.5m) (1pc)	W0300605R	
Cable (15m) (1pc)	W0300607R	
Connector (1pc)	W03X0934-2R	W03X0934-4R




svetskompaniet.se

	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)		Retaining Cap (blister 1pc)		Shield Cap (blister 2pcs)
Cutting process							
40A	W03X0893-1A	W03X0893-5R	W03X0893-2A		W03X0893-10A		
50A	W03X0893-1A	W03X0893-5R	W03X0893-3A		W03X0893-10A		
60A	W03X0893-1A	W03X0893-5R	W03X0893-15A		W03X0893-10A		
Shielded 40A	W03X0893-1A	W03X0893-5R		W03X0893-16A		W03X0893-11A	W03X0893-12A
Shielded 50A	W03X0893-1A	W03X0893-5R		W03X0893-6A		W03X0893-11A	W03X0893-12A
Shielded 60A	W03X0893-1A	W03X0893-5R		W03X0893-17A		W03X0893-11A	W03X0893-12A
Gouging	W03X0893-1A	W03X0893-5R		W03X0893-9A		W03X0893-11A	W03X0893-13A

LC65

Tomahawk 1025

	LC65
Torch (Hand 7.5m) (1pc)	PTH-061A-CX-7M5A
Torch (Hand 15m) (1pc)	PTH-061A-CX-15MA
Handle (1pc)	W0300609R
Head (1pc)	W0300608R
Cooling Kit (blister 1pc)	W03X0893-49R
Cable (7.5m) (1pc)	W0300604R
Cable (15m) (1pc)	W0300606R
Connector (1pc)	W03X0934-4R




svetskompaniet.se

Cutting process	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)			Retaining Cap (blister 1pc)		Spacer (blister 2pcs)	Shield Cap (blister 2pcs)	
40A	W03X0893-25A	W03X0893-50R		W03X0893-27A		W03X0893-41A		W03X0893-14R		
50A	W03X0893-25A	W03X0893-50R		W03X0893-28A		W03X0893-41A		W03X0893-14R		
60A	W03X0893-25A	W03X0893-50R		W03X0893-29A		W03X0893-41A		W03X0893-14R		
Dir Contact 40A	W03X0893-25A	W03X0893-50R	W03X0893-26A			W03X0893-41A				
Contact 50A	W03X0893-25A	W03X0893-50R			W03X0893-33A		W03X0893-43A			W03X0893-44A
Contact 60A	W03X0893-25A	W03X0893-50R			W03X0893-34A		W03X0893-43A			W03X0893-44A
Gouging	W03X0893-25A	W03X0893-50R			W03X0893-39A		W03X0893-43A		W03X0893-48A	








LC65M

Tomahawk 1025

	LC65M
Torch (Machine 7.5m) (1pc)	PTM-061A-CX-7M5A
Torch (Machine 15m) (1pc)	PTM-061A-CX-15MA
Positioning tube (1pc)	W0300603R
Head (1pc)	W0300610R
Cooling Kit (blister 1pc)	W03X0893-49R
Cable (7.5m) (1pc)	W0300605R
Cable (15m) (1pc)	W0300607R
Connector (1pc)	W03X0934-4R




svetskompaniet.se

Cutting process	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)		Retaining Cap (blister 1pc)		Shield Cap (blister 2pcs)
							
40A	W03X0893-25A	W03X0893-50R	W03X0893-27A		W03X0893-41A		
50A	W03X0893-25A	W03X0893-50R	W03X0893-28A		W03X0893-41A		
60A	W03X0893-25A	W03X0893-50R	W03X0893-29A		W03X0893-41A		
Shielded 40A	W03X0893-25A	W03X0893-50R		W03X0893-52A		W03X0893-43A	W03X0893-46A
Shielded 50A	W03X0893-25A	W03X0893-50R		W03X0893-33A		W03X0893-43A	W03X0893-46A
Shielded 60A	W03X0893-25A	W03X0893-50R		W03X0893-34A		W03X0893-43A	W03X0893-46A
Gouging	W03X0893-25A	W03X0893-50R		W03X0893-39A		W03X0893-43A	W03X0893-48A

LC80 & LC100

PC1030

	LC80	LC100
Torch (Hand 7.5m) (1pc)	PTH-080A-CX-7M5A	PTH-100A-CX-7M5A
Torch (Hand 15m) (1pc)	PTH-080A-CX-15MA	PTH-100A-CX-15MA
Handle (1pc)	W0300609R	
Head (1pc)	W0300608R	
Cooling Kit (blister 1pc)	W03X0893-49R	
Cable (7.5m) (1pc)	W0300611R	
Cable (15m) (1pc)	W0300613R	
Connector (1pc)	W03X0934-7R	W03X0934-8R




svetskompaniet.se

Cutting process	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)			Retaining Cap (blister 1pc)		Spacer (blister 2pcs)	Shield Cap (blister 2pcs)	
40A	W03X0893-25A	W03X0893-50R		W03X0893-27A		W03X0893-41A		W03X0893-14R		
50A	W03X0893-25A	W03X0893-50R		W03X0893-28A		W03X0893-41A		W03X0893-14R		
60A	W03X0893-25A	W03X0893-50R		W03X0893-29A		W03X0893-41A		W03X0893-14R		
70A	W03X0893-25A	W03X0893-51R		W03X0893-30A		W03X0893-42A		W03X0893-14R		
80A	W03X0893-25A	W03X0893-51R		W03X0893-31A		W03X0893-42A		W03X0893-14R		
100A	W03X0893-25A	W03X0893-51R		W03X0893-32A		W03X0893-42A		W03X0893-14R		
Dir Contact 40A	W03X0893-25A	W03X0893-50R	W03X0893-26A			W03X0893-41A				
Contact 50A	W03X0893-25A	W03X0893-50R			W03X0893-33A		W03X0893-43A			W03X0893-44A
Contact 60A	W03X0893-25A	W03X0893-50R			W03X0893-34A		W03X0893-43A			W03X0893-44A
Contact 70A	W03X0893-25A	W03X0893-51R			W03X0893-35A		W03X0893-43A			W03X0893-45A
Contact 80A	W03X0893-25A	W03X0893-51R			W03X0893-36A		W03X0893-43A			W03X0893-45A
Contact 100A	W03X0893-25A	W03X0893-51R			W03X0893-37A		W03X0893-43A			W03X0893-45A
Gouging	W03X0893-25A	W03X0893-51R			W03X0893-38A		W03X0893-43A		W03X0893-48A	








LC80M & LC100M

PC1030

	LC80M	LC100M
Torch (Machine 7.5m) (1pc)	PTM-080A-CX-7M5A	PTM-100A-CX-7M5A
Torch (Machine 15m) (1pc)	PTM-080A-CX-15MA	PTM-100A-CX-15MA
Positioning tube (1pc)	W0300603R	
Head (1pc)	W0300610R	
Cooling Kit (blister 1pc)	W03X0893-49R	
Cable (7.5m) (1pc)	W0300612R	
Cable (15m) (1pc)	W0300614R	
Connector (1pc)	W03X0934-7R	W03X0934-8R




svetskompaniet.se

Cutting process	Electrode (blister 5pcs)	Gas Distr. (blister 3pcs)	Tip (blister 5pcs)		Retaining Cap (blister 1pc)		Shield Cap (blister 2pcs)
							
40A	W03X0893-25A	W03X0893-50R	W03X0893-27A		W03X0893-41A		
50A	W03X0893-25A	W03X0893-50R	W03X0893-28A		W03X0893-41A		
60A	W03X0893-25A	W03X0893-50R	W03X0893-29A		W03X0893-41A		
70A	W03X0893-25A	W03X0893-51R	W03X0893-30A		W03X0893-42A		
80A	W03X0893-25A	W03X0893-51R	W03X0893-31A		W03X0893-42A		
100A	W03X0893-25A	W03X0893-51R	W03X0893-32A		W03X0893-42A		
Shielded 40A	W03X0893-25A	W03X0893-50R		W03X0893-52A		W03X0893-43A	W03X0893-46A
Shielded 50A	W03X0893-25A	W03X0893-50R		W03X0893-33A		W03X0893-43A	W03X0893-46A
Shielded 60A	W03X0893-25A	W03X0893-50R		W03X0893-34A		W03X0893-43A	W03X0893-46A
Shielded 70A	W03X0893-25A	W03X0893-51R		W03X0893-35A		W03X0893-43A	W03X0893-47A
Shielded 80A	W03X0893-25A	W03X0893-51R		W03X0893-36A		W03X0893-43A	W03X0893-47A
Shielded 100A	W03X0893-25A	W03X0893-51R		W03X0893-37A		W03X0893-43A	W03X0893-47A
Gouging	W03X0893-25A	W03X0893-51R		W03X0893-38A		W03X0893-43A	W03X0893-48A








LC105

Tomahawk1538

	LC105
Torch (Hand 7.5m) (1pc)	PTH-101A-CX-7M5A
Torch (Hand 15m) (1pc)	PTH-101A-CX-15MA
Handle (1pc)	W0300609R
Head (1pc)	W0300618R
Insulation Kit (blister 1pc)	W03X0893-71R
Cable (7.5m) (1pc)	W0300620R
Cable (15m) (1pc)	W0300622R
Connector (1pc)	W03X0934-8R




svetskompaniet.se

	Electrode (blister 5pcs)	Gas Distr. (blister 2pcs)	Tip (blister 5pcs)	Retaining Cap (blister 1pc)	Spacer (blister 2pcs)	Shield Cap (blister 2pcs)	
Cutting process							
40A	W03X0893-60A	W03X0893-70R	W03X0893-61A	W03X0893-66A	W03X0893-14R	W03X0893-68A	
60A	W03X0893-60A	W03X0893-70R	W03X0893-62A	W03X0893-66A	W03X0893-14R	W03X0893-68A	
80A	W03X0893-60A	W03X0893-70R	W03X0893-63A	W03X0893-66A	W03X0893-14R	W03X0893-68A	
100A	W03X0893-60A	W03X0893-70R	W03X0893-64A	W03X0893-66A	W03X0893-14R	W03X0893-68A	
Contact 40A	W03X0893-60A	W03X0893-70R	W03X0893-61A	W03X0893-66A			W03X0893-67A
Contact 60A	W03X0893-60A	W03X0893-70R	W03X0893-62A	W03X0893-66A			W03X0893-67A
Contact 80A	W03X0893-60A	W03X0893-70R	W03X0893-63A	W03X0893-66A			W03X0893-67A
Contact 100A	W03X0893-60A	W03X0893-70R	W03X0893-64A	W03X0893-66A			W03X0893-67A
Gouging	W03X0893-60A	W03X0893-70R	W03X0893-65A	W03X0893-66A		W03X0893-69A	






LC105M

Tomahawk1538

	LC105
Torch (Machine 7.5m) (1pc)	PTM-101A-CX-7M5A
Torch (Machine 15m) (1pc)	PTM-101A-CX-15MA
Positioning tube (1pc)	W0300603R
Head (1pc)	W0300619R
Insulation Kit (blister 1pc)	W03X0893-71R
Cable (7.5m) (1pc)	W0300621R
Cable (15m) (1pc)	W0300623R
Connector (1pc)	W03X0934-8R



svetskompaniet.se

Cutting process	Electrode (blister 5pcs) 	Gas Distr. (blister 2pcs) 	Tip (blister 5pcs) 	Retaining Cap (blister 1pc) 	Shield Cap (blister 2pcs) 
40A	W03X0893-60A	W03X0893-70R	W03X0893-61A	W03X0893-66A	W03X0893-68A
60A	W03X0893-60A	W03X0893-70R	W03X0893-62A	W03X0893-66A	W03X0893-68A
80A	W03X0893-60A	W03X0893-70R	W03X0893-63A	W03X0893-66A	W03X0893-68A
100A	W03X0893-60A	W03X0893-70R	W03X0893-64A	W03X0893-66A	W03X0893-68A
Gouging	W03X0893-60A	W03X0893-70R	W03X0893-65A	W03X0893-66A	W03X0893-69A